


IMPORTANT NOTICE

(change made subsequent to the printing of the manual)

In the interest of continuous improvement we have changed the start-up screen in the factory preset. The Display will now show the Coins target pattern preselected.

To access Iron Mask, press the Iron Mask shortcut button.



In high trash areas you might like to experiment with higher levels of Iron Mask than the factory preset level of -6.